


Company Model	Drawing	No.	Spare part	Quantity	Material	size	L	H	DN	PN	WEIGHT
S1001		1	body	1	brass	1/2"	32,8	45	18	16	120
		2	spring	1	stainless	3/4"	41,5	51	22	16	180
		3	disc	1	POM	1"	47	54	28	16	240
		4	rubber gasket	1	NBR	1 1/4"	57,5	57,5	37	16	330
		5	bonnet	1	brass	1 1/2"	68	68,5	42	16	500
						2"	80	72,5	55	16	700
						2 1/2"	103	90,5	67	16	1550
						3"	110	97	78	16	1900
						4"	142	112	101,5	16	3000
						thread according to ISO228					
						Working Temperature: -20°C ≤ t ≤ +110 °C					